



# G2Shield – onboard steppers

Using TinyG2/G2core on an Arduino Due, connect up to 6 onboard stepper controllers (not included) and limit switches for both XYZ and ABC direction. Directly connect laser/spindle and coolant relay to control a small CNC or laser cutter/engraver.

## List of components

### SMD:

Qty	Value	Device	Parts
1	BSS138	SOT23	Q1
12	100n	C-1206	C1-C12
18	10k	R-1206	R1-R18

### Through-hole:

Qty	Value	Device	Parts
6	100uF/35V	C-pol-3.5-8	C13-C18
2	2-pin	Con-DG300-5	SPINDLE, VMOTOR
1	2-pin	Con-kk	COOLANT
1	3-pin	Con-kk	SUPPLY
1	4-pin	Con-kk	SPINDLE_INTERFACE
1	1x10,4x1x8,2x18	Con-pinhead	DUEG2
6	1x4	Con-pinhead	MOTOR1-6
6	2x3	Con-pinhead	CONFIG1-6
1	2x4	Con-pinhead	Control switches
1	2x6	Con-pinhead	Limit switches ABC/XYZ (in 1-12)
12	1x8	Con-socket	DRIVER1-6
1		Switch	RESET
1	IRL540N	TO-220	Q2

## Introduction

Thanks for buying this G2Shield kit with onboard steppers! SMD components have been premounted for your convenience, so only the remaining through-hole parts need to be mounted. Make sure you read the complete instructions before you start mounting. Assembly can be done by an experienced hobbyist in about half an hour.

### List of components

Please check if the list of components is complete. If desired, you can adapt them to your needs.

### Tools

- ✓ Soldering iron and solder
- ✓ Multi-meter (voltage and resistance)
- ✓ Side-cutting pliers

### General instructions

#### Mounting

With the SMD components premounted, mounting the remaining through-hole connectors is straightforward. As usual go from components with the lowest height to the highest height.

Hint: to make sure the female pinheaders for the stepper controllers have the right distance you can connect a stepper during soldering! Same applies to the Arduino Due connection on the bottom side of the pcb.

#### External components

Connect external components according to the instructions shown in the schematic:

- External VMOTOR voltage 12-24V (make sure the voltage is supported by the stepper drivers, or laser/spindle)
- Stepper drivers
  - Designed for Pololu A4988 or DRV8825 drivers (not included)
  - Using jumpers (not included) on M0-M2 you can select the amount of microstepping
- Limit switches
  - 12 general purpose inputs, labeled as Xmin/max to Cmin/max on the pcb, G2core allows them to be freely configured
  - Both NC and NO supported by G2core
- Control switches
  - not yet supported by G2core
- Coolant relay
  - For external 5V relays
- Laser/spindle control
  - Onboard IRL540N mosfet driver for direct connection of spindle/laser
  - Interface using enable/direction/pwm

#### G2core software

For a thorough introduction to the G2core software, please check the Synthetos website. A quick introduction on how to get G2core and use it in combination with the G2Shield:

<https://www.djuke.nl/en/support/18-cnc/46-using-g2-core>

#### Testing

Do not connect external components yet until below voltages

are checked!

Connect the G2Shield on top of a Arduino Due with G2core software. Power the Arduino Due using USB or external supply.

- The voltage between corresponding pins (1-2, 3-4 etc) of the limit switch inputs is 3.3V
- The voltage on pin 1 of the Motor connectors should be equal to the external voltage on VMOTOR
- The voltage on COOLANT-1 is 5V

Now, the external components can be connected and tested from G2core. The easiest way to do so is to clone the GIT repository from <https://github.com/Djuke-DIYAudio/g2> and build the firmware with settings\_Djuke\_test.h

Connect to the Arduino Due using USB and a terminal program.

Useful test commands:

Command	Description
\$in	Shows input values
\$clear	Clears alarm state
M3 S100	Enables spindle clockwise with 100% PWM output
M4 S50	Enables spindle anti-clockwise with 50% PWM output
M5	Disable spindle
M7	Enable coolant relay
M9	Disable coolant relay
G0 x#	Move x-axis to position # (similar for y/z/a/b/c axis)

# Schematic

